

Material Safety Data Sheet

Revision Date: 2/18/91

NA = Not Applicable NE = Not Established

Section 1. General Information

Product name: **Duripal**
Chemical Name: NA
Chemical Family: Silicates
Formula: Proprietary
Manufacturer: **IPA Systems, Inc.**
2745 North Amber Street, Philadelphia, Pa. 19134
Phone: 800-523-3834 • 215-425-6607
Fax: 215-425-6234
E-mail: info@ipasystems.com
Website: www.ipasystems.com

Emergency Phone Number - Chemtrec: 800-424-9300

Section 2. Hazardous Ingredients

<u>Name:</u>	<u>C.A.S. No.</u>	<u>Percent</u>
Aqueous silicate solution	1312-76-1	6.0

Section 3. Physical Data

Boiling Point: NA
Vapor Pressure (mm Hg.): NA
Vapor Density (Air = 1): NA
Solubility in Water: Complete
Appearance and Odor: Clear water-like liquid, odorless

Specific Gravity: (H₂O = 1): 1.0 – 1.2
Percent Volatile by Volume: NA
Evaporation Rate: NA
pH: 11.0 – 13.0

Section 4. Fire and Explosion Hazard Data

Flash Point: None
Autoignition Temperature: NE
Flammable Limits: LEL = NA UEL = NA
Extinguishing Media: NA
Special Fire Fighting Procedures: NA
Unusual Fire and Explosion Hazards: NA

Material Safety Data Sheet

Revision Date: 2/18/91

NA = Not Applicable NE = Not Established

Section 5. Health Hazard Data

OSHA PEL: NA

ACGIH TLV: NA

Carcinogen – NTP Program: No

Carcinogen – IARC Program: No

Symptoms of Exposure: Spray mist may damage respiratory tract.

Medical Conditions Aggravated by Exposure: NE

Routes of Entry: Inhalation, Skin

Emergency and First Aid Procedures:

Eye Contact: Immediately flush well with large amounts of running water for at least 15 minutes. Seek medical attention immediately.

Skin Contact: Wash affected area with water.

Inhalation: Remove victim to fresh air.

Section 6. Reactivity Data

Stability: Stable

Conditions to Avoid: Flammable hydrogen gas may be produced on prolonged contact with metals such as aluminum, tin, lead and zinc.

Incompatibility (Materials to Avoid Contact): Product will etch glass. Gels when mixed with acid.

Hazardous Decomposition or By-Products: None

Hazardous Polymerization: Will not occur.

Section 7. Procedures for Safe Handling and Use

Spill Response: Mop up and flush small spills (100 gallons max.) with plenty of water. Dike and flush large spills.

Waste Disposal Method: In small quantities (100 gallons max.) flush with water. Large quantities, neutralize with acid and land fill solids according to prevailing local regulations.

Section 8. Control Measures

Eye Protection: Chemical goggles and face shield.

Respiratory Protection: Use NIOSH approved mist respirator where spray occurs.

Skin Protection: Rubber protective gloves.

Ventilation: Local and mechanical where necessary.

Other Protection: Safety shower and eyewash

Material Safety Data Sheet

Revision Date: 2/18/91

NA = Not Applicable NE = Not Established

Section 9. Special Precautions

Hygienic Practices in Handling and Storage: Avoid contact with eyes, skin or clothing. Wash after handling. Wash contaminated clothing before reuse.

Precautions for Repair and Maintenance of Contaminated Equipment: NE

Other Precautions: Keep from freezing.